la marzocco USA technical bulletin 187

new firmware for gb5 x-s
March 19, 2024

We would like to inform you about the release of new machine firmware for GB5 X-S.

The new firmware, version 1.0.0-RC14, fixes a bug that may cause the heating cycle not to work correctly while showing a false fixed temperature on display, as well as some other minor bugs and mistranslations.

For machines built prior to and without IoT hardware, contact Solutions for instructions on manually loading the firmware from a USB stick. This new firmware is available on the La Marzocco Pro App for connected machines.

Download the Pro App:

Android - https://play.google.com/store/apps/details?id=com.lamarzocco.professional

iOS - https://apps.apple.com/us/app/la-marzocco-pro/id1586341630

Do not hesitate to contact our solutions team with any questions you may have about this technical bulletin.
solutions.usa@lamarzocco.com
206.706.9104 x 101