

La Marzocco Technical Bulletin # 132



Vulcano Swift new power board.

March 15, 2017

The Vulcano Swift power board has been modified and now has different connections. Only the new version of the power board is available as a replacement part. In the event the power board needs to be replaced it will be necessary to pay attention to the serial number to confirm if a retrofit kit is necessary.

All Vulcano Swift starting from serial number 1349118 have the new board. The retrofit kit is not necessary. If the serial number is 1349117 or lower, the retrofit kit is required.

The retrofit kit includes a new power board, new push-button board and all necessary cables. Everything in green in the following diagram is included in the retrofit kit and will need to be replaced:



In Verde sono segnati i componenti da sostituire

The green components must be replaced



The part number of the retrofit kit is as follows:

M.1.039 Vulcano Retrofit board kit, 120V (SN up to 1349117)

The part number of the power board has not changed but is only available in the new revision:

M.1.291 Vulcano, Swift Power Board

Please do not hesitate to contact your La Marzocco sales representative or our solutions team with any questions you have about this update.

solutions.usa@lamarzocco.com