



HANDMADE IN FLORENCE


**La Marzocco Technical Bulletin #51 – November the 22nd 2011
GB/5 & FB/80 New Steam Valve Assembly**

We would like to inform you about the latest modification on the GB/ 5 and FB/ 80 steam valve.

The new steam valve permits a correct maneuver of the shaft which controls the opening and closing of steam flow.


This steam valve is now being used in production from serial no. **GB/ FB 5000**

B.1.001.02.K Kit “retrofit” per rubinetto vapore GB/ 5
Retrofit kit for GB/ 5 steam valve



B.1.001.02.K	item	part number	q.ty	item	part number	q.ty
	01	I.1.046	1	05	F.1.033	1
	02	L120/2A	1	06	DADO4M	1
	03	F.1.006.01	1	07	H.1.005	5
04	A.1.022	1	08	A.1.002.01	1	

B.1.001.02.K2 Kit manutenzione nuovo rubinetto vapore
 Rebuild kit for GB/ 5 steam valve



B.1.001.02.K2	part numeber	q.ty	part number	q.ty
	H.1.005	5	L260/1A	1
	F.4.001	1	I.4.001	1
	H.2.001	1	H.1.004	1
	H.2.002	1	H.2.003	1
	L100/D	1	H.1.003	1
	F.1.033	1	L120/A	1

B.1.001.02

Rubinetto vapore inclinato completo di manopola e tappo
GB/ 5 steam valve complete



The above kits and complete valve will shortly be available for purchase
from Nuova Ricambi: annika@nuovaricambi.it

For further information please contact the After-Sales Department :

Enrico Wurm: enrico@amarzocco.com
Ettore Scagliola: ettore@amarzocco.com